

STEMME GmbH & Co. KG Design Org. No. EB 11	Service Bulletin		Documentnumber: A31-10-052
	Revision of the Flight Manual S10-VT and of the Maintenance Manuals S10-V and S10-VT		Am.-Index: 01.b
			Page 4 (of 4)

The following maintenance manuals **S10-VT** are affected by the modification:

Doc. No.	Language	Issue	Affected Pages:
A40-11-120	German version (original version)	01.01.1998	i, ii, iv...viii, 2-2, 3-16, 3-24...3-27, 3-55, 4-1, 4-2, 5-6, 5-9, 5-10, 6-9, 6-13, 7-5, 7-11, 7-19...7-23, 7-28, 7-29, 9-3, 11-1, Deckblatt Anhang A, Deckblatt Anhang C
A40-11-121	English (JAA-version)	01.01.1998	i, ii, iv...viii, 2-2, 3-16; 3-24...3-27, 3-55, 4-1, 4-2, 5-6, 5-9, 5-10, 6-8, 6-9, 6-13, 7-5, 7-11, 7-19...7-23, 7-28, 7-29, 8-2, 9-3, 11-1, Cover Annex A, Cover Annex C
A40-11-122	English (FAA-version)	19.12.1997	ditto

The corrections to these S10-VT manuals, which have been made necessary by the modification detailed above, are uniformly referred to as "Amendment No. 08, Date of Amendment: 11.11.1999".

6. Mass and balance:

Not affected.

7. Material:

Set of exchange pages for both Flight Manual (S10-VT only) and Maintenance Manual according to section 5.2.

8. Associated documents:

None.

9. Accomplishment and log entry:

The incorporation of the manual pages may be carried out by the operator himself. The regulations on the keeping of service records must be adhered to.

Stemme GmbH & Co. KG - Airworthiness Department / LBA approved

prepared:	Sign	checked:	Sign	Date:	Supersedes issue of:
Montag		Ellwanger		11.04.2000	---,---,-----