

**Subject:** Spark plug EYQUEM A 755 L, Part Number: 205.123.100.000 and  
Spark plug EYQUEM A 755, Part Number: 170.123.101.000

**Affected engine models:** All engine models:

**L 1700**  
**L 2000**  
**L 2400 EB, L 2400 EE**

**Background information:** Production of current spark plug EYQUEM A 755 L, P/N: 205.123.100.000 and EYQUEM A 755, P/N: 170.123.101.000 terminated.

**Priority:** On replacement of spark plugs

**Compliance:** The spark plug EYQUEM A 755 L, P/N: 205.123.100.000 is replaced by spark plug LIMBACH LB-L41.0, P/N: 205.123.101.000.  
The spark plug EYQUEM A 755, P/N: 170.123.101.000 is replaced by spark plug LIMBACH LB-N41.0, P/N: 170.123.103.000.

When using the new type spark plugs a new ignition harness must be used also.

The ignition harness P/N: 205.123.010.000 is replaced by ignition harnesses P/N: 205.123.011.000 or 205.123.012.000

The ignition harness P/N: 205.123.020.000 is replaced by ignition harnesses P/N: 205.123.021.000 or 205.123.022.000.

The ignition harness P/N: 170.123.020.000 is replaced by ignition harnesses P/N: 170.123.021.000 or 170.123.022.000.

The ignition harness P/N: 209.123.020.000 is replaced by ignition harnesses P/N: 209.123.021.000 or 209.123.022.000.

References in the manuals are to be added in handwriting.

**Caution:** Engine specific data does not change.

**Note:** This document has been translated to the best of our knowledge. In case of doubt however only the German original shall be considered authoritative.

**Source:** Limbach Flugmotoren GmbH & Co. KG, Kotthausener Str. 5, D-53639 Königswinter, Germany  
Tel. +49/2244/9201-0, Fax: +49/2244/9201-30, E-Mail: [sales@limflug.de](mailto:sales@limflug.de) [www.limflug.de](http://www.limflug.de)

**Approval:** This Technical Bulletin was approved according to the procedures of the EASA Design Organisation No.: EASA.21J.270