

# SERVICE BULLETIN

## PUBLICATION INDEX FOR ROTAX® AIRCRAFT ENGINES

SB-2ST-000 R13

SB-912 i-000 R1

SB-912-000 R13

SB-914-000 R13

### **MANDATORY**

#### Repeating symbols:

Please, pay attention to the following symbols throughout the Service Bulletin emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.
- | || A revision bar outside of page margin indicates a change to text or graphic.

#### 1) Planning information

##### 1.1) Engines affected

All versions of the engine type:

all 2-stroke UL aircraft engines	(Series/pre-series)
all 2-stroke certified aircraft engines	(Series/pre-series)
912	(Series/pre-series)
912 i	(Series/pre-series)
914	(Series/pre-series)

##### 1.2) Concurrent ASB/SB/SI und SL

none

##### 1.3) Reason

List of valid documentation according to Part 21A.57 "Instructions for continued airworthiness"

##### 1.4) Subject

Publication index for ROTAX® aircraft engines.

##### 1.5) Compliance

MANDATORY

For maintaining the airworthiness we strongly advise to update the documentation to the latest revision in accordance with the enclosed list in the chapter 4.

##### 1.6) Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.048.

## 2) Material Information

none

## 3) Accomplishment / Instructions

Incorporation / replacement of the respective documentation.

## 4) Appendix

In the following table (list of current documentation, Issue 2012.07.17, page 1 - 16) all the effective documentation is listed in English for all the engine types as stated in the section 1.1) Engines affected.

◆ NOTE: Because of the multitude of documentation a continual updating of the tables is not possible. Updating will be effected with each new issue or revision but at least twice a year.

The current documentation (current issue) or relevant revisions (replacement pages) are available at any ROTAX<sup>®</sup> authorized Distributor or their Service Centers in printed version or at the ROTAX<sup>®</sup> AIRCRAFT ENGINES Homepage.

**[www.flyrotax.com](http://www.flyrotax.com)**

in electronic version.

▲ WARNING: Non-compliance with these recommendations could result in engine damage, personal injury or death!

Approval of translation to best knowledge and judgment - in any case the original text in German language and the metric units (SI-system) are authoritative.

21. DECEMBER 2012

Copyright - BRP-Powertrain GmbH & CO KG. All rights reserved.

SB-2ST-000 R13  
SB-912 i-000 R1  
SB-912-000 R13  
SB-914-000 R13  
page 2 of 2

005690

**Publication Index for ROTAX 2-stroke aircraft engines and all versions of ROTAX aircraft engine type 912 / 912 i / 914**

**ROTAX**  
AIRCRAFT ENGINES



document type	engine type	Issue	Revision	Date	P.no.	Title
CD-447	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	16	01.04.2011	899745	Documentation CD-Rom ROTAX 912 and 914 (Series) and 2-stroke aircraft engines
CD-503	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	16	01.04.2011	899745	Documentation CD-Rom ROTAX 912 and 914 (Series) and 2-stroke aircraft engines
CD-582	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	16	01.04.2011	899745	Documentation CD-Rom ROTAX 912 and 914 (Series) and 2-stroke aircraft engines
CD-912	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	16	01.04.2011	899745	Documentation CD-Rom ROTAX 912 and 914 (Series) and 2-stroke aircraft engines
CD-914	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	16	01.04.2011	899745	Documentation CD-Rom ROTAX 912 and 914 (Series) and 2-stroke aircraft engines
DIV-2ST	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	24.08.2007		Customer Service Information Report
DIV-2ST	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	0	01.11.2003		ROTAX Aircraft Engine Registration Card
DIV-912i	912 iS, 912 iSc	0	0	19.07.2012		BRP Utility and Diagnostic Software B.U.D.S. Aircraft V2.1
DIV-914	914 F, 914 UL	0	0	01.01.2001		Monitoring-Program TLR 4.6a
DIV-914	914 F, 914 UL	0	0	01.01.2001		Monitoring-Program TLR 4.5a
DIV-914	914 F, 914 UL	0	0	01.01.2001		Monitoring-Program TLR 4.3a
IM-275	275	1	0	01.11.1990		Installation Manual 275 (not available - use german version)
IM-447	447 UL, 503 UL, 582 UL	0	0	01.05.1999	899482	Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
IM-463	463	1	0	01.04.1992		Installation Manual 463 - (not available - use german version)
IM-503	447 UL, 503 UL, 582 UL	0	0	01.05.1999	899482	Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
IM-535	535 A, 535 B, 535 C	1	0	01.12.1982		Installation Manual 535 (Serie) - (not available - use german version)
IM-582	447 UL, 503 UL, 582 UL	0	0	01.05.1999	899482	Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
IM-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	2	0	01.09.2012	898643	Installation Manual ROTAX 912 Series
IM-912i	912 iS, 912 iSc	1	1	10.09.2012	898647	Installation Manual ROTAX 912 i Series, Rev. 1
IM-912i	912 iS, 912 iSc	1	1	10.09.2012		Revision pages for Installation Manual ROTAX 912 i Series, Rev. 1
IM-914	914 F, 914 UL	2	0	01.07.2008	897817	Installation Manual 914 Series
IPC-185	185	0	0	01.01.1982	n.a.	Spare parts list for engine 185
IPC-275	275	0	0	01.07.1988	n.a.	Spare parts list for engine 275 (Nr. 656)
IPC-277	277 UL	0	2	01.07.1993	n.a.	Spare parts list for engine 277 UL (Nr. 491)
IPC-377	377 UL	0	4	01.04.1993	n.a.	Spare parts list for engine 377 UL (Nr. 624)
IPC-447	447 UL, 503 UL, 582 UL, 618 UL	3	1	01.04.2011	899147	Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI
IPC-462	462 UL	0	0	01.10.1988	n.a.	Spare parts list for engine 462 UL (Nr. 660)
IPC-501	501	1	0	01.01.1979	n.a.	Spare parts list for engine 501 (Nr. 306)
IPC-503	447 UL, 503 UL, 582 UL, 618 UL	3	1	01.04.2011	899147	Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI
IPC-505	505, 505 A	0	0	01.09.1990	n.a.	parts list for engine type 505/505A (Nr. 744)
IPC-505	505 A	1	1	01.07.1993	n.a.	Spare parts list for engine 505 A (Nr. 805)
IPC-508	508 UL	0	0	01.08.1988	n.a.	Spare parts list for engine 508 (Nr. 646)
IPC-532-000	532 UL	0	2	01.07.1993	n.a.	Spare parts list for engine 532 UL (Nr. 648)
IPC-535	535 C	0	0	01.04.1988	n.a.	Illustrated Parts Catalog 535 C (Nr. 645)
IPC-535	535 A, 535 B	0	0	01.07.1983	n.a.	Illustrated Parts Catalog 535 A+B (Nr. 448)

document type	engine type	Issue	Revision	Date	P.no.	Title
IPC-582	447 UL, 503 UL, 582 UL, 618 UL	3	1	01.04.2011	899147	Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI
IPC-618	447 UL, 503 UL, 582 UL, 618 UL	3	1	01.04.2011	899147	Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI
IPC-912	912 UL	0	1	01.11.1994	n.a.	Illustrated parts catalog 912 UL (No. 825)
IPC-912	912 A, 912 UL	0	3	01.07.1992	n.a.	Illustrated parts catalog 912 UL (No. 700)
IPC-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	2	2	01.05.2009	899471	Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL
IPC-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	2	2	01.09.2011		Exchange pages for Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL, Edition 2, Revision 2
IPC-912i	912 iS, 912 iSc	1	0	10.09.2012	899475	Illustrated Parts Catalog for ROTAX Engine Type 912 i Series
IPC-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	2	2	01.05.2009	899471	Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL
IPC-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	2	2	01.09.2011		Exchange pages for Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL, Edition 2, Revision 2
MM-447	447 UL, 503 UL, 582 UL	0	0	01.05.1999	899484	Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
MM-503	447 UL, 503 UL, 582 UL	0	0	01.05.1999	899484	Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
MM-582	447 UL, 503 UL, 582 UL	0	0	01.05.1999	899484	Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
MMH-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	1	01.01.2008	899603	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 1
MMH-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	2	01.07.2008	899603	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 2
MMH-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	3	01.05.2007	899603	Maintenance Manual (Heavy) for ROTAX 912 and 914 Series
MMH-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	3	01.10.2010	899603	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 3
MMH-912i	912 iS, 912 iSc	1	0	10.09.2012		Maintenance Manual (Heavy) for ROTAX 912 i Series
MMH-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	1	01.01.2008	899603	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 1
MMH-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	2	01.07.2008	899603	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 2
MMH-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	3	01.05.2007	899603	Maintenance Manual (Heavy) for ROTAX 912 and 914 Series
MMH-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	3	01.10.2010	899603	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 3
MML-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	3	0	01.09.2012	899191	Maintenance Manual 912 Series (Line Maintenance)
MML-912i	912 iS, 912 iSc	0	1	10.09.2012		Revision pages for Maintenance Manual (Line) for ROTAX 912 i Series, Rev. 1
MML-912i	912 iS, 912 iSc	1	1	10.09.2012	898742	Maintenance Manual (Line) ROTAX 912 i Series
MML-914	914 F, 914 UL	2	1	01.07.2010	899608	Maintenance Manual (Line) for ROTAX 914 Series
MML-914	914 F, 914 UL	2	1	01.07.2010	899608	Revision Pages for Maintenance Manual (Line) for 914 Series
OHM-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	2	2	01.01.2010	898701	Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities)
OHM-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	2	2	01.01.2010	898701	Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities)
OHMA-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	3	01.03.2010	897797	Appendices to Overhaul Manual 912 and 914 Series, only available in English language (only available for authorized distributors and overhaul facilities)
OHMA-914	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	1	3	01.03.2010	897797	Appendices to Overhaul Manual 912 and 914 Series, only available in English language (only available for authorized distributors and overhaul facilities)
OM-275	275	1	2	15.01.1998	n.a.	Operator's manual 275
OM-277	277 UL	0	4	01.03.1988	n.a.	Operators manual 277 UL
OM-377-000	377 UL, 447 UL, 503 UL	19	0	01.06.1994	n.a.	Operator's Manual 377-447-503 UL CB
OM-447	447 UL, 503 UL, 582 UL	2	0	01.09.2010	899121	Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99
OM-447-000	377 UL, 447 UL, 503 UL	19	0	01.06.1994	n.a.	Operator's Manual 377-447-503 UL CB
OM-462	462 UL	0	2	01.07.1993	897623	Operators manual 462 UL
OM-463	463	1	0	12.06.1992	n.a.	Operator's manual 463 - (not available - use german version)
OM-501	501	1	2	01.11.1997	n.a.	Operator's manual 501
OM-503	447 UL, 503 UL, 582 UL	2	0	01.09.2010	899121	Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99
OM-503-000	377 UL, 447 UL, 503 UL	19	0	01.06.1994	n.a.	Operator's Manual 377-447-503 UL CB

document type	engine type	Issue	Revision	Date	P.no.	Title
OM-505	505	2	0	30.04.1992	n.a.	Operator`s manual 505 with decompressor
OM-505	505	2	0	30.04.1992	n.a.	Operator`s manual 505 without decompressor
OM-505	505 A	2	0	29.01.1992	n.a.	Operators manual 505 A without decompressor
OM-505	505 A	2	0	30.04.1992	n.a.	Operator`s manual 505 A with decompressor
OM-508	508 UL	0	3	01.07.1993	n.a.	Operators manual 508 UL
OM-532	532 UL	0	4	01.03.1990	n.a.	Operators manual 532 UL
OM-535	535 A, 535 B	2	0	01.01.1992	n.a.	Operator`s manual 535 A (dual carburetor horizontal) Operator`s manual 535 B (dual carburetor vertical)
OM-535-000	535 C	2	0	01.01.1992	n.a.	Operator`s manual 535 C (single carburetor)
OM-582	447 UL, 503 UL, 582 UL	2	0	01.09.2010	899121	Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99
OM-618-000	618 UL	1	0	01.06.1994	n.a.	Operators manual ROTAX 618 UL (preliminary)
OM-642	642	0	0	01.06.1975	n.a.	Operator`s manual 642
OM-912	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	3	0	01.09.2012	899649	Operators Manual 912 Series
OM-912i	912 iS, 912 iSc	1	1	10.09.2012	898740	Operators Manual ROTAX 912 i Series, Rev. 1
OM-912i	912 iS, 912 iSc	1	1	10.09.2012		Revision pages for Operators Manual ROTAX 912 i Series, Rev.1
OM-914	914 F, 914 UL	2	1	01.04.2011	899645	Operators manual 914 series
OM-914	914 F, 914 UL	2	1	01.04.2011	899645	Revision Pages for Operators Manual 914 Series, Revision 1
RM-275	275	1	1	01.10.1991	n.a.	Repair manual 275
RM-277	277 UL	0	2	01.01.1993	n.a.	Repair manual 277 UL
RM-377	377 UL, 447 UL, 503 UL	0	1	01.12.1989	n.a.	Repair manual engine types 377-447-503 UL CB
RM-447	377 UL, 447 UL, 503 UL	0	1	01.12.1989	n.a.	Repair manual engine types 377-447-503 UL CB
RM-462	462 UL, 532 UL, 582 UL	0	1	01.10.1994	899081	Repair manual 462-532-582 UL
RM-501	501, 505, 505 A	1	3	01.01.1993	n.a.	Repair manual 501/505 (Serie)
RM-503	377 UL, 447 UL, 503 UL	0	1	01.12.1989	n.a.	Repair manual engine types 377-447-503 UL CB
RM-505	501, 505, 505 A	1	3	01.01.1993	n.a.	Repair manual 501/505 (Serie)
RM-532	462 UL, 532 UL, 582 UL	0	1	01.10.1994	899081	Repair manual 462-532-582 UL
RM-535-000	535 A, 535 B, 535 C	1	0	01.01.1993	n.a.	Repair manual 535 (Serie)
RM-582	462 UL, 532 UL, 582 UL	0	1	01.10.1994	899081	Repair manual 462-532-582 UL
**SB-275	275, 501, 505, 505 A, 535 A, 535 B, 535 C	0	1	04.05.2007		New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
**SB-501	501, 505, 505 A	0	0	01.08.1989	n.a.	Piston pin bearing, conversion to reinforced design **(for 501 see SB-505-005)
**SB-501	501, 505, 505 A	0	0	02.12.1997	n.a.	TBO of ROTAX engine type 501, 505 and 505 A. **(for 501 see SB-505-007)
**SB-501	275, 501, 505, 505 A, 535 A, 535 B, 535 C	0	1	04.05.2007		New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
**SB-505	275, 501, 505, 505 A, 535 A, 535 B, 535 C	0	1	04.05.2007		New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
**SB-535	275, 501, 505, 505 A, 535 A, 535 B, 535 C	0	1	04.05.2007		New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
ASB-912-051	912 A, 912 F, 912 S, 914 F	0	0	13.10.2006		Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-912-051-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	13.10.2006		Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-912-053	912 A, 912 F, 912 S	0	0	20.02.2007		Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053, latest edition
ASB-912-053-UL	912 UL, 912 ULS, 912 ULSFR	0	0	20.02.2007		Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053, latest edition
ASB-912-059	912 A, 912 F, 912 S, 914 F	0	0	01.01.2012		CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059/SB-914-042 latest edition
ASB-912-059-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.01.2012		CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059UL/SB-914-042UL latest edition
ASB-912-060	912 S, 914 F	0	0	26.01.2012		Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-912-060-UL	912 UL, 912 ULS, 914 UL	0	0	26.01.2012		Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-912-061	912 A, 912 F, 912 S	0	1	31.05.2012		Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series)
ASB-912-061-UL	912 UL, 912 ULS	0	1	31.05.2012		Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series)
ASB-914-034	912 A, 912 F, 912 S, 914 F	0	0	13.10.2006		Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition

document type	engine type	Issue	Revision	Date	P.no.	Title
ASB-914-034-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	13.10.2006		Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-914-042	912 A, 912 F, 912 S, 914 F	0	0	01.01.2012		CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059/SB-914-042 latest edition
ASB-914-042-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.01.2012		CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059UL/SB-914-042UL latest edition
ASB-914-043	912 S, 914 F	0	0	26.01.2012		Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-914-043-UL	912 UL, 912 ULS, 914 UL	0	0	26.01.2012		Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
SB-2ST-000	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	13	21.12.2012		Publication Index for ROTAX Aircraft Engines
SB-2ST-001	582 UL	0	0	01.12.2001	n.a.	Checking or replacement of tension spring on exhaust system for ROTAX engine type 582 UL
SB-2ST-002	582 UL	0	0	01.03.2002	n.a.	Modified rotary valve cover for ROTAX engine type 582 UL
SB-505-001	505	0	0	26.02.1986	n.a.	Studs 840 585 (M8x177) connecting cylinders to crankcase (8x)
SB-505-002	505	0	0	20.09.1988	n.a.	Conversion of engine types 505 into 505 A (type certificate data sheet TW 3/78, issue no. 5
SB-505-003	505, 505 A	0	0	20.09.1988	n.a.	Check of ignition timing after exchange of an electronic box
SB-505-004	505, 505 A	0	0	13.04.1989	n.a.	Examination of the starter gear for cracks.
SB-505-005	501, 505, 505 A	0	0	01.08.1989	n.a.	Piston pin bearing, conversion to reinforced design *(for 501 see SB-505-005)
SB-505-006	505, 505 A	0	0	29.01.1992	n.a.	Introduction of a new electronic box with a modified wiring on the stator plate.
SB-505-007	501, 505, 505 A	0	0	02.12.1997	n.a.	TBO of ROTAX engine type 501, 505 and 505 A. *(for 501 see SB-505-007)
SB-505-008	505, 505 A	0	0	22.01.1999	n.a.	Magneto housing for ROTAX engine type 505 (series)
SB-505-009	505, 505 A	0	1	01.03.2003	n.a.	New charging coil assy. with support for Rotax engine type 505
SB-505-010	275, 501, 505, 505 A, 535 A, 535 B, 535 C	0	1	04.05.2007		New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
SB-535-001	535 A, 535 B	0	0	31.01.1984	n.a.	Flywheel on drive side
SB-535-002	535 A, 535 B	0	0	05.12.1985	n.a.	Coil brace 866 780 connecting charging coil with lighting coil on armature plate assy.
SB-535-003	535 A, 535 B, 535 C	0	0	20.09.1988	n.a.	Check of ignition timing after exchange of an electronic box.
SB-535-004	535 A, 535 B, 535 C	0	0	21.03.1989	n.a.	Fixation of charging coil and lighting coil on armature plate assy.
SB-535-005	535 A, 535 B, 535 C	0	0	13.04.1989	n.a.	Examination of the starter gear for cracks.
SB-535-006	535 A, 535 B, 535 C	0	0	05.06.1992	n.a.	Introduction of a new electronic box with a modified wiring on the stator plate.
SB-535-007	535 A, 535 B, 535 C	0	1	01.02.1999	n.a.	Magneto housing for ROTAX engine type 535 (series).
SB-535-008	535 A, 535 B, 535 C	0	1	28.01.2005	n.a.	New charging coil assy. with support for Rotax engine type 535
SB-535-009	275, 501, 505, 505 A, 535 A, 535 B, 535 C	0	1	04.05.2007		New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
SB-912-000	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	13	21.12.2012		Publication Index for ROTAX Aircraft Engines
SB-912-001	912 A	0	0	13.08.1992	897681	Engine type 912 A, Ignition unit with resistor spark plug
SB-912-002	912 A	0	1	29.11.1993	n.a.	Ignition for ROTAX 912 A
SB-912-003	912 A	0	0	28.09.1993	n.a.	CANCELLED - Operators manual for ROTAX 912 A - superseded by Operators manual 912 Series, current edition
SB-912-004	912 A	0	2	14.12.2009	n.a.	Extension of time between overhauls (TBO) for ROTAX engine type 912 A (Series)
SB-912-004-UL	912 UL	0	2	14.12.2009	n.a.	Extension of time between overhauls (TBO) for ROTAX engine type 912 UL (Series)
SB-912-005	912 A	0	2	29.07.1996	n.a.	Special inspection to increase the TBO for engine 912 A Serie
SB-912-005	912 A	0	3	14.12.2009	n.a.	Special inspection to increase the TBO for ROTAX engine type 912 A (Series)

document type	engine type	Issue	Revision	Date	P.no.	Title
SB-912-005-UL	912 UL	0	0	14.12.2009	n.a.	Special inspection to increase the TBO for ROTAX engine type 912 UL (Series)
SB-912-006	912 A	0	0	28.11.1994	n.a.	Grounding cable for electronic module of ROTAX Engine series Type 912 A
SB-912-007	912 A	0	0	01.02.1995	n.a.	Ground connection for pick up wiring, ROTAX Engine Series Type 912 A
SB-912-007-UL	912 UL	0	0	20.12.2007		Ground connection for pick-up wiring for ROTAX engine type 912 (Series)
SB-912-008	912 A	0	0	24.08.1995	n.a.	Electronic module with pi-filter, ROTAX Engine Series 912 A
SB-912-009	912 A	0	0	12.09.1995	n.a.	Contamination of carburetors, ROTAX 912 A (series)
SB-912-010	912 A, 912 F	0	0	08.02.1996	n.a.	Fitting of a carburetor support, ROTAX 912 A/F (series)
SB-912-010-UL	912 UL	0	0	20.12.2007		Fitting of a carburetor support for ROTAX engine type 912 (Series)
SB-912-011	912 A, 912 F	0	1	01.11.1999	n.a.	CANCELLED - Use of an adapted propeller governor on Rotax engine type 912 A3 and 912 F3, superseded by SB-912-052/SB-914-035, latest edition
SB-912-012	912 A	0	0	13.08.1996	n.a.	Modification on ROTAX 912 A4
SB-912-013	912 A, 912 F, 912 S, 912 UL, 912 ULS	0	0	29.07.1996	n.a.	CANCELLED - Motor oil for ROTAX 912 Series - superseded by SI-18-1997 latest edition
SB-912-014	912 A, 912 F	0	2	14.12.2009	n.a.	Extension of time between overhauls (TBO) for ROTAX engine type 912 A and 912 F (Series)
SB-912-015	912 A, 912 F	0	0	29.07.1996	n.a.	Replacement of rocker arms on ROTAX 912 A/F (series)
SB-912-015-UL	912 UL	0	0	20.12.2007		Replacement of rocker arms for ROTAX engine type 912 (Series)
SB-912-016	912 A	0	0	13.08.1996	n.a.	External alternator for engine type 912, model A2, A3 and A4
SB-912-017	912 A, 912 F	0	1	20.12.2007	n.a.	Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-912-017-UL	912 UL	0	1	20.12.2007		Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-912-018	912 A	0	1	18.03.1997	n.a.	Cam shaft check engine type ROTAX 912 A (series)
SB-912-019	912 A	0	0	09.07.1997	n.a.	Propeller gear box for ROTAX 912 A3
SB-912-020	912 A, 912 F	0	1	10.02.1998	897682	Fuel pump for Engine type ROTAX 912 F and 912 A (series)
SB-912-020-UL	912 UL	0	0	20.12.2007		Replacement of the fuel pump part no. 996592 for ROTAX engine type 912 (Series)
SB-912-021	912 F	0	0	17.12.1997	n.a.	CANCELLED - Operator's manual for ROTAX 912 F - superseded by Operator's manual 912 Series, latest edition
SB-912-022	912 A, 912 F, 912 S, 914 F	0	0	01.03.2001	898081	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (series)
SB-912-022-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	13.03.2001	898083	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (Series)
SB-912-023	912 A, 912 F	0	0	25.05.1998	n.a.	Inspection of the fuel pump kit, part no. 996.594 <sup>7</sup>
SB-912-024	912 A, 912 F	0	0	22.10.1998	n.a.	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T1, superseded by SB-912-052/SB-914-035, latest edition
SB-912-025	912 A, 912 F	0	0	22.10.1998	n.a.	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition
SB-912-026	912 A, 912 F, 914 F	0	3	01.12.1999	n.a.	Checking and replacement of stator assy.
SB-912-026-UL	912 UL, 912 ULS, 914 UL	0	3	01.12.1999	n.a.	Checking and replacement of stator assy.
SB-912-027	912 A, 912 F, 914 F	0	1	01.02.2000	n.a.	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-912-027-UL	912 UL, 914 UL	0	1	01.02.2000	n.a.	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-912-028	912 A, 912 F, 912 S, 914 F	0	1	01.11.2002	n.a.	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (Series)
SB-912-028-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	01.11.2002	n.a.	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (series)
SB-912-029	912 A, 912 F, 912 S, 914 F	0	3	11.07.2006	n.a.	Checking of crankcase on ROTAX engine type 912 and 914 (Series)
SB-912-029-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	3	11.07.2006	n.a.	Checking of the crankcase on ROTAX engine type 912 and 914 (Series)
SB-912-030	912 A, 912 F, 912 S, 914 F	0	1	01.02.2004	n.a.	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-912-030-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	01.02.2004	n.a.	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-912-031	912 A, 912 F, 912 S	0	0	01.10.2001	n.a.	Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine tpye 912 (series)
SB-912-031-UL	912 UL, 912 ULS, 912 ULSFR	0	0	01.10.2001	n.a.	Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine tpye 912 (series)

document type	engine type	Issue	Revision	Date	P.no.	Title
SB-912-032	912 A	0	0	01.10.2001	898181	Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 A (series)
SB-912-032-UL	912 UL	0	0	01.10.2001	898183	Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 UL
SB-912-033	912 A, 912 F, 912 S, 914 F	0	0	01.08.2002	n.a.	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-912-033-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.08.2002	n.a.	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-912-034	912 A	0	0	01.03.2002	n.a.	Checking of oil pump attachment screw for ROTAX engine type 912 A (Series)
SB-912-034-UL	912 UL	0	0	01.03.2002	n.a.	Checking of oil pump attachment screw for ROTAX engine type 912 UL (Series)
SB-912-035	912 A, 912 F, 912 S, 914 F	0	1	01.09.2002	n.a.	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-912-035-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	01.09.2002	n.a.	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-912-036	912 A, 912 F, 912 S, 914 F	0	1	23.01.2007	n.a.	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040/SB-914-026, latest edition
SB-912-036-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	23.01.2007	n.a.	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040UL/SB-914-026UL, latest edition
SB-912-037	912 A, 912 F, 912 S, 914 F	0	1	01.10.2003	n.a.	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-912-037-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.10.2002	n.a.	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-912-038	912 A, 912 F, 912 S, 914 F	0	0	01.11.2002		CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-912-038-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.11.2002		CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-912-039	912 A, 912 F, 912 S, 914 F	0	0	01.12.2002		Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-912-039-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.12.2002		Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-912-040	912 A, 912 F, 912 S, 914 F	0	1	01.08.2003		Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-912-040-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.04.2003		Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-912-041	912 A, 912 F, 912 S, 914 F	0	2	25.03.2010		Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-912-041-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	2	25.03.2010		Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-912-042	912 S	0	1	01.04.2004	n.a.	Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S
SB-912-042-UL	912 ULS, 912 ULSFR	0	1	01.04.2004	n.a.	Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S
SB-912-043	912 A, 912 F, 912 S, 914 F	0	2	10.11.2006		Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-912-043-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	28.08.2006		Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-912-044	912 A, 912 F	0	1	28.05.2010		Use of the Rotax supplied airbox for all Rotax engine types 912 A/F (Series)
SB-912-044-UL	912 UL	0	1	28.05.2010		Use of the Rotax supplied airbox for all Rotax engine types 912 UL (Series)
SB-912-045	912 A, 912 F, 912 S, 914 F	0	0	19.11.2004		Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-912-045-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	19.11.2004		Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-912-046	912 S, 914 F	0	0	26.07.2005		Check of the support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-912-046-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	26.07.2005		Check of support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-912-047	912 S, 914 F	0	0	29.07.2005		Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-912-047-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	29.07.2005		Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-912-048	912 A, 912 F, 912 S, 914 F	0	0	23.09.2005		Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-912-048-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	23.09.2005		Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)



document type	engine type	Issue	Revision	Date	P.no.	Title
SB-912-049	912 A, 912 F, 912 S	0	0	24.05.2006		Checking eccenters and fuel pump plungers for Rotax engine type 912 (series)
SB-912-049-UL	912 UL, 912 ULS, 912 ULSFR	0	0	24.05.2006		Checking eccenters and fuel pump plungers for Rotax engine type 912 (series)
SB-912-050	912 A, 912 F, 912 S	0	0	24.05.2006		CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition
SB-912-050-UL	912 UL, 912 ULS, 912 ULSFR	0	0	24.05.2006		CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition
SB-912-051	912 A, 912 F, 912 S, 914 F	0	0	30.01.2008		Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-912-051-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	30.01.2008		Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-912-052	912 A, 912 F, 912 S, 914 F	0	2	17.10.2008		Installation / Use of governors for Rotax engine type 912 and 914
SB-912-052-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	29.05.2007		Installation / Use of governors for Rotax engine type 912 and 914
SB-912-053	912 A, 912 F, 912 S	0	0	13.04.2007		Replacement of fuel pump for Rotax engine type 912 (Series)
SB-912-053-UL	912 UL, 912 ULS, 912 ULSFR	0	0	13.04.2007		Replacement of fuel pump for Rotax engine type 912 (Series)
SB-912-054	912 A, 912 F, 912 S	0	0	29.05.2007		Checking or replacement of flexible fuel line for Rotax engine type 912 (Series)
SB-912-054-UL	912 UL, 912 ULS, 912 ULSFR	0	0	29.05.2007		Checking or replacement of flexible fuel line for Rotax engine type 912 (Series)
SB-912-055	912 A, 912 F, 912 S, 914 F	0	0	31.08.2007		Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-912-055-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	31.08.2007		Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-912-056	912 S, 914 F	0	1	05.08.2008		Replacement of the propeller gearbox for some Rotax engines type 912/914 (Series)
SB-912-056-UL	912 ULS, 912 ULSFR, 914 UL	0	1	05.08.2008		Replacement of the propeller gearbox for some ROTAX engines type 912/914 (Series)
SB-912-057	912 A, 912 F, 912 S	0	0	14.12.2009		Extension of time between overhauls (TBO) for ROTAX engine type 912 (Series)
SB-912-057-UL	912 UL, 912 ULS, 912 ULSFR	0	0	14.12.2009		Extension of time between overhauls (TBO) for ROTAX engine type 912 (Series)
SB-912-058	912 A, 912 F, 912 S, 914 F	0	0	15.04.2011		Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)
SB-912-058-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	15.04.2011		Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)
SB-912-059	912 A, 912 F, 912 S, 914 F	0	0	01.01.2012		Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SB-912-059-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.01.2012		Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SB-912i-000	912 iS, 912 iSc	0	1	21.12.2012		Publication Index for ROTAX Aircraft Engines
SB-914-000	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	13	21.12.2012		Publication Index for ROTAX Aircraft Engines
SB-914-001	914 F	0	0	06.02.1997	n.a.	CANCELLED - Use of an adapted propeller governor on engine type ROTAX 914 F3, superseded by SB-912-052/SB-914-035, latest edition
SB-914-002	914 F	0	0	24.02.1997	n.a.	Modification of engine type ROTAX 914 F3
SB-914-003	914 F	0	0	09.07.1997	n.a.	Calibration of the mixture enrichment jet of engine type ROTAX 914 F (series)
SB-914-003-UL	914 UL	0	0	20.12.2007		Calibration of the mixture enrichment jet for ROTAX engine type 914 (Series)
SB-914-004	914 F	0	0	27.08.1997	n.a.	Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX 914 (series)
SB-914-004-UL	914 UL	0	0	20.12.2007		Checking of the banjo bolt in the pressure oil line of turbocharger for ROTAX engine type 914 (Series)
SB-914-005	914 F	0	0	29.07.1998	n.a.	Introduction of a turbo charger with a modified wastegate on Rotax 914
SB-914-005-UL	914 UL	0	0	20.12.2007		Introduction of a turbocharger with modified waste-gate for ROTAX engine type 914 (Series)
SB-914-006	914 F	0	1	01.10.2002	n.a.	Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series).
SB-914-006-UL	914 UL	0	0	01.10.2002		Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series).

document type	engine type	Issue	Revision	Date	P.no.	Title
SB-914-007	914 F	0	0	05.06.1998	n.a.	ROTAX engine type 914 F (series), check / replacement of the turbo oil pressure line and pipe clamps
SB-914-007-UL	914 UL	0	0	20.12.2007		Check/replacement of the turbo oil pressure line and pipe clamps for ROTAX engine type 914 (Series)
SB-914-008	914 F	0	0	05.06.1998	n.a.	ROTAX engine type 914 F (series) check / replacement of the wastegate servo cable
SB-914-008-UL	914 UL	0	0	20.12.2007		Check/replacement of the waste-gate servo cable for ROTAX engine type 914 (Series)
SB-914-009	914 F	0	0	22.10.1998	n.a.	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition
SB-914-010	912 A, 912 F, 914 F	0	1	01.02.2000	n.a.	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-914-010-UL	912 UL, 914 UL	0	1	01.02.2000	n.a.	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-914-011	912 A, 912 F, 912 S, 914 F	0	0	01.03.2001	898081	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (series)
SB-914-011-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	13.03.2001	898083	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (Series)
SB-914-012	914 F	0	0	29.09.1998	n.a.	ROTAX engine series type 914 F, verification of the wiring harness
SB-914-012-UL	914 UL	0	0	20.12.2007		Verification of the wiring harness for ROTAX engine type 914 (Series)
SB-914-013	914 F	0	0	31.03.1999	n.a.	Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for engine Type 914 F (series)
SB-914-013-UL	914 UL	0	0	20.12.2007		Turbocharge control unit (TCU) with software level D according to RTCA DO 178 B for ROTAX engine type 914 (Series)
SB-914-014	912 A, 912 F, 914 F	0	3	01.12.1999	n.a.	Checking and replacement of stator assy.
SB-914-014-UL	912 UL, 912 ULS, 914 UL	0	3	01.12.1999	n.a.	Checking and replacement of stator assy.
SB-914-015	914 F	0	0	01.01.2001	n.a.	Checking or replacement of the exhaust muffler of reduced noise emission part no. 979405 for ROTAX engine type 914 F
SB-914-016	912 A, 912 F, 912 S, 914 F	0	1	01.11.2002	n.a.	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (Series)
SB-914-016-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	01.11.2002	n.a.	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (series)
SB-914-017	914 F	0	1	01.07.2002	n.a.	Checking or replacement of exhaust bend on ROTAX engine type 914 (Series)
SB-914-017-UL	914 UL	0	1	01.07.2002	n.a.	Checking or replacement of the exhaust bend on ROTAX engine type 914 (series)
SB-914-018	912 A, 912 F, 912 S, 914 F	0	3	11.07.2006	n.a.	Checking of crankcase on ROTAX engine type 912 and 914 (Series)
SB-914-018-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	3	11.07.2006	n.a.	Checking of the crankcase on ROTAX engine type 912 and 914 (Series)
SB-914-019	912 A, 912 F, 912 S, 914 F	0	1	01.02.2004	n.a.	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-914-019-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	01.02.2004	n.a.	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-914-020	912 A, 912 F, 912 S, 914 F	0	0	01.08.2002	n.a.	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-914-020-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.08.2002	n.a.	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-914-021	912 A, 912 F, 912 S, 914 F	0	1	01.09.2002	n.a.	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-914-021-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	01.09.2002	n.a.	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-914-022	912 A, 912 F, 912 S, 914 F	0	1	23.01.2007	n.a.	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040/SB-914-026, latest edition
SB-914-022-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	23.01.2007	n.a.	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040UL/SB-914-026UL, latest edition
SB-914-023	912 A, 912 F, 912 S, 914 F	0	1	01.10.2003	n.a.	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-914-023-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.10.2002	n.a.	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-914-024	912 A, 912 F, 912 S, 914 F	0	0	01.11.2002		CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-914-024-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.11.2002		CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)

document type	engine type	Issue	Revision	Date	P.no.	Title
SB-914-025	912 A, 912 F, 912 S, 914 F	0	0	01.12.2002		Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-914-025-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.12.2002		Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-914-026	912 A, 912 F, 912 S, 914 F	0	1	01.08.2003		Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-914-026-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.04.2003		Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-914-027	912 A, 912 F, 912 S, 914 F	0	2	25.03.2010		Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-914-027-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	2	25.03.2010		Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-914-028	914 F	0	1	08.11.2004	n.a.	Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series)
SB-914-028-UL	914 UL	0	1	08.11.2004	n.a.	Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series)
SB-914-029	912 A, 912 F, 912 S, 914 F	0	2	10.11.2006		Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-914-029-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	28.08.2006		Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-914-030	912 A, 912 F, 912 S, 914 F	0	0	19.11.2004		Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-914-030-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	19.11.2004		Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-914-031	912 S, 914 F	0	0	26.07.2005		Check of the support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-914-031-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	26.07.2005		Check of support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-914-032	912 S, 914 F	0	0	29.07.2005		Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-914-032-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	29.07.2005		Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-914-033	912 A, 912 F, 912 S, 914 F	0	0	23.09.2005		Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-914-033-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	23.09.2005		Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-914-034	912 A, 912 F, 912 S, 914 F	0	0	30.01.2008		Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-914-034-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	30.01.2008		Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-914-035	912 A, 912 F, 912 S, 914 F	0	2	17.10.2008		Installation / Use of governors for Rotax engine type 912 and 914
SB-914-035-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	1	29.05.2007		Installation / Use of governors for Rotax engine type 912 and 914
SB-914-036	912 A, 912 F, 912 S, 914 F	0	0	31.08.2007		Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-914-036-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	31.08.2007		Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-914-037	914 F	0	0	20.12.2007		Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-914-037-UL	914 UL	0	0	20.12.2007		Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-914-038	912 S, 914 F	0	1	05.08.2008		Replacement of the propeller gearbox for some Rotax engines type 912/914 (Series)
SB-914-038-UL	912 ULS, 912 ULSFR, 914 UL	0	1	05.08.2008		Replacement of the propeller gearbox for some ROTAX engines type 912/914 (Series)
SB-914-039	914 F	0	0	25.03.2010		Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series)
SB-914-039-UL	914 UL	0	0	25.03.2010		Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series)
SB-914-040	914 F	0	0	10.03.2011		Replacement of fuel pressure regulator part no. 887130 for ROTAX engine type 914 (Series)
SB-914-040-UL	914 UL	0	0	10.03.2011		Replacement of fuel pressure regulator assy. part no. 887130 for ROTAX engine type 914 (Series)
SB-914-041	912 A, 912 F, 912 S, 914 F	0	0	15.04.2011		Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)
SB-914-041-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	15.04.2011		Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)
SB-914-042	912 A, 912 F, 912 S, 914 F	0	0	01.01.2012		Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)

document type	engine type	Issue	Revision	Date	P.no.	Title
SB-914-042-UL	912 UL, 912 ULS, 912 ULSFR, 914 UL	0	0	01.01.2012		Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SI-01-1985	377 UL, 447 UL, 462 UL, 503 UL, 532 UL	0	0	01.04.1985	n.a.	UL-Propeller-Gear
SI-01-1988	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 532 UL	0	0	01.01.1988	n.a.	Function test of rectifier regulator
SI-01-1989	503 UL	0	0	01.03.1989	n.a.	Fan drive of engine Type 503
SI-01-1991	532 UL, 582 UL	0	0	01.02.1991	n.a.	Rotary valve shaft sealing for ROTAX 532 UL and 582 UL
SI-01-1992	912 UL	0	0	01.07.1992	897691	Engine type 912 UL, ignition unit with resistor spark plug
SI-01-1993	582 UL	0	0	01.01.1993	n.a.	ROTAX 582 UL DCDI - making of pick-up
SI-01-1994	912 A, 912 UL	0	0	01.01.1994	897695	Electronic-box for ROTAX 912 A + UL
SI-01-1995	912 UL	0	1	01.04.1995	n.a.	CANCELLED - Ground connection for pick-up wiring, ROTAX engine Series Type 912 UL, superseded by SB-912-007 UL, latest edition
SI-01-1998	912 UL	0	1	01.02.1998	n.a.	CANCELLED - Fuel pump 996592 (pump with screw fittings) 912 (series), superseded by SB-912-020 UL, latest edition
SI-02-1984	277 UL	0	0	25.01.1984	n.a.	UL-Propeller-Gear 277
SI-02-1985	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 532 UL	0	0	01.05.1985	n.a.	Increase of ignition voltage on BOSCH contact ignition
SI-02-1991	503 UL, 582 UL, 618 UL	0	0	01.02.1991	n.a.	Tightening torque increase on 'C' gearboxes for UL-engines.
SI-02-1992	912 A, 912 UL	0	0	01.12.1992	n.a.	Coolant expansion tank ROTAX 912
SI-02-1993	912 UL	0	0	01.01.1993	n.a.	CANCELLED - Overload clutch for Rotax engine 912 UL, superseded by relevant Maintenance Manual, latest edition
SI-02-1995	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	2	0	01.08.1995	n.a.	Contamination of carburetors, ROTAX-series 912
SI-02-1996	912 A, 912 UL	0	0	01.02.1996	n.a.	Rectifier regulator, Rotax Series 912
SI-02-1997	912 UL	0	0	01.02.1997	n.a.	Camshaft check on ROTAX engine Type 912 UL (series)
SI-02-1998	914 F, 914 UL	0	0	01.06.1998	n.a.	CANCELLED - ROTAX engine type 914, check / replacement of the turbo oil pressure line and pipe clamps, superseded by SB-914-007 UL, latest edition
SI-03-1985	277 UL	0	0	01.09.1985	n.a.	UL-Propeller-Gear 277
SI-03-1989	377 UL, 447 UL, 503 UL, 532 UL	0	0	01.06.1989	n.a.	Matching a propeller to ROTAX UL-Engines.
SI-03-1991	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.04.1991	n.a.	Daily and Pre-Flight-Check - Maintenance plan for all ROTAX engines
SI-03-1993	912 UL	0	0	01.02.1993	n.a.	Ignition unit of ROTAX 912 UL
SI-03-1994	912 A, 912 UL	0	0	01.12.1994	n.a.	Sensor and gauge for oil pressure indication-ROTAX 912
SI-03-1995	912 A, 912 UL	0	0	01.02.1995	n.a.	CANCELLED - Cracks in the carburetor flange, engine series type 912, superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-03-1996	462 UL, 532 UL, 582 UL, 618 UL	0	1	01.09.1999	n.a.	Rotary valve shaft seal leakage at Rotax engine type 462 UL / 532 UL / 582 UL and 618 UL
SI-03-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.01.1999	n.a.	CANCELLED - Coolant (antifreeze) mixtures for ROTAX engine type 912/914 (Series) - superseded by relevant Operators Manual, latest edition
SI-03-1998	912 A, 912 F, 912 S, 912 UL, 914 F, 914 UL	0	1	01.02.2004	n.a.	Engine start at low temperatures at Rotax engine type 912 and 914 (Series)
SI-03-1999	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.02.1999	n.a.	Standardization of the crankcase for ROTAX engines 912 and 914
SI-04-1986	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL	0	0	01.09.1986	n.a.	Possible causes for piston seizures or holes in pistons
SI-04-1987	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL	1	0	01.05.1990	n.a.	Ultralight engines-unexpected engine stops
SI-04-1989	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL	0	0	01.01.1989	n.a.	Use of tool for cageless piston pin needle bearing
SI-04-1990	582 UL	0	0	01.09.1990	n.a.	Starter gear - electric starter, magneto side, on engine 582 UL
SI-04-1993	582 UL	0	0	01.09.1993	n.a.	Crankcase modifications - ROTAX 582 DCDI
SI-04-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 UL, 914 UL	0	0	01.02.1994	n.a.	Carburetor icing on UL-engines
SI-04-1995	912 A, 912 F, 912 UL	0	0	01.05.1995	n.a.	Floats with a new shape, engine Series Type 912
SI-04-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	3	23.01.2007	898135	CANCELLED - Venting of lubrication system for Rotax engine type 912 and 914 (Series), superseded by SI-912-018/SI-914-020, latest edition
SI-04-1998	914 F, 914 UL	0	1	01.06.1998	n.a.	CANCELLED - ROTAX engine type 914 F (series) Replacement of the waste gate servo cable, superseded by SB-914-008 UL, latest edition
SI-05-1988	377 UL, 447 UL, 462 UL, 503 UL, 532 UL	0	0	01.04.1990	n.a.	Gearbox fixation on UL-engines type 377 to 532 UL
SI-05-1990	503 UL, 582 UL	0	1	01.12.1990	n.a.	Disturbance of tachometer 966 072 for 503 UL C.D.I. and 582 UL with DUCATI ignition unit

document type	engine type	Issue	Revision	Date	P.no.	Title
SI-05-1991	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.12.1991	n.a.	Piston for ROTAX UL engines (2-stroke)
SI-05-1994	912 A, 912 UL	0	0	01.03.1994	n.a.	Banjo Bolt ROTAX 912
SI-05-1995	912 UL	0	2	01.07.1996	n.a.	External alternator for engine series type 912 UL, Mod. 94
SI-05-1996	447 UL, 503 UL	0	0	01.03.1997	n.a.	Cracks in the carburetor socket, ROTAX 447 and 503 UL
SI-05-1997	912 A, 912 F, 912 UL, 914 F, 914 UL	0	1	01.04.1997	n.a.	Exhaust flange of ROTAX engines 912/914 (series)
SI-05-1998	914 F, 914 UL	0	0	01.06.1998	n.a.	Acceptable cracks in the turbine housing of the turbo charger for engine 914
SI-05-1999	914 UL	0	0	01.10.1999	n.a.	CANCELLED - Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for ROTAX engine Type 914 F (series), superseded by SB-914-013 UL, latest edition
SI-06-1986	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL	0	0	01.12.1986	n.a.	UL-Reduction gear box
SI-06-1987	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL	0	0	01.07.1987	n.a.	Engine-Instruments
SI-06-1993	582 UL	0	0	01.09.1993	n.a.	ROTAX 582 UL carb adapter
SI-06-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.07.1994	n.a.	Incorrect Model fuel pumps without bleed hole, ROTAX 2-cycle engines
SI-06-1995	912 UL	0	2	01.07.1996	n.a.	External alternator for engine series type 912 UL, Mod. 89 and 91
SI-06-1996	503 UL, 582 UL, 618 UL	0	0	01.03.1997	n.a.	Modifications on reduction gearbox 'C' and 'E'
SI-06-1997	912 A, 912 F, 912 UL, 914 F, 914 UL	0	1	18.02.2005	n.a.	Friction torque check of propeller gear with overload clutch on Rotax engine type 912 and 914 (Series)
SI-06-1998	447 UL, 503 UL, 532 UL, 582 UL, 618 UL	0	1	01.07.2001	n.a.	Amendment on reduction gearbox type 'C' and type 'E' for 2-stroke UL aircraft engines
SI-06-1999	912 S, 912 ULS	0	0	01.01.1998	n.a.	ROTAX engine Type 912 ULS/S, Oil consumption
SI-07-1987	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL	1	0	01.04.1990	n.a.	Fuel consumption, 2-stroke UL-Engine
SI-07-1991	447 UL, 508 UL	0	0	01.05.1991	897550	Wiring diag. for 447 UL SCDI and 508 UL SCDI in conj. with electr. tachometer
SI-07-1993	447 UL	0	0	01.09.1993	n.a.	Revolution counter for ROTAX 447 SCDI
SI-07-1994	582 UL	0	0	01.07.1994	n.a.	ROTAX 582 UL crankshaft
SI-07-1995	277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.02.1999	n.a.	New airfilter with securing tab
SI-07-1996	912 UL	0	0	01.09.1996	n.a.	CANCELLED - Replacement of rocker arms on ROTAX 912 UL (series), superseded by SB-912-015 UL, latest edition
SI-07-1997	914 UL	0	0	01.07.1997	n.a.	CANCELLED - Calibration of the mixture enrichment jet of ROTAX 914 UL (series), superseded by SB-914-003 UL, latest edition
SI-07-1998	503 UL	0	0	12.10.1998	n.a.	'B' type gearbox installation, ROTAX 503 UL DCDI (all versions)
SI-08-1987	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL	0	0	01.06.1990	n.a.	Influence of ambient air temperature and barometric pressure on engine performance and carb calibration
SI-08-1991	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.06.1991	n.a.	Safety-check of the BING-carburetors used in all ROTAX UL-engines
SI-08-1993	912 A, 912 UL	0	0	01.10.1993		CANCELLED - General overhaul of ROTAX 912 A/UL, superseded by SB for TBO Extension, latest edition
SI-08-1994	582 UL	0	0	01.05.1994	n.a.	Attaching of water pump housing on ROTAX 582 UL
SI-08-1995	912 UL	0	1	01.12.1995	n.a.	CANCELLED - Fitting of a carburetor support, Rotax Series 912, superseded by SB-912-010 UL, latest edition
SI-08-1996	618 UL	0	0	01.03.1997	n.a.	Installation of oversize pistons, ROTAX 618 UL
SI-08-1998	914 UL	0	1	01.02.1999	n.a.	CANCELLED - ROTAX engine series type 914 UL, verification of the wiring harness, superseded by SB-914-012 UL, latest edition
SI-08-1999	447 UL, 503 UL, 582 UL	0	0	01.02.1999		CANCELLED - Documentations for 447 - 503 - 582 - 582 Mod. 99, superseded by SL-2ST-002, latest edition
SI-09-1991	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.11.1991	897701	Installation Instructions for ROTAX UL-engines
SI-09-1993	618 UL	0	0	01.11.1993	n.a.	Assembly instructions for ROTAX 618 water pump cover
SI-09-1994	503 UL, 532 UL, 582 UL, 618 UL	0	2	01.01.2004	897891	Installation Instruction of UL reduction gearbox type 'C' and 'CL'
SI-09-1996	914 UL	0	0	01.03.1998	n.a.	ROTAX 914 UL exchange of the oilpump housing
SI-09-1997	503 UL	0	0	01.07.1997	n.a.	Exchange of piston pins, ROTAX 503 UL
SI-10-1987	503 UL	0	0	01.11.1987	n.a.	503 UL- FREE AIR Version
SI-10-1991	912 A, 912 UL	0	0	01.09.1991	n.a.	Water distributor for ROTAX 912 A and 912 UL
SI-10-1994	503 UL, 532 UL, 582 UL, 618 UL	0	2	01.01.2004	897892	Installation Instruction of UL reduction gearbox type 'E' and 'EL'
SI-10-1996	277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL	0	0	01.05.1997	n.a.	Piston pin circlip installation (2-stroke UL-engines)

document type	engine type	Issue	Revision	Date	P.no.	Title
SI-10-1999	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.03.1999	n.a.	Illustrated Parts Catalog (IPC) for ROTAX engines 912 / 914 (series)
SI-11-1987	377 UL, 447 UL, 503 UL, 532 UL	0	0	01.11.1987	n.a.	Exhaust systems for 377/447/462/503/532
SI-11-1991	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.12.1992	n.a.	Propeller mass moment of inertia
SI-11-1994	503 UL	1	0	01.06.1994	897893	Subsequent install. or retrofit of an oil-Pump for separate oil Lubrication
SI-11-1996	277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL	0	0	01.01.1998	n.a.	Engine preservation for 2-stroke- UL- engines
SI-11-1997	914 F, 914 UL	0	0	01.12.1997	n.a.	Adjustment or verification of the wastegate position on ROTAX 914
SI-12-1991	508 UL	0	0	01.12.1992	n.a.	508 UL-Valve Cover Attachment
SI-12-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL	0	2	01.01.2004	897890	Installation Instruction of UL reduction gearbox Type 'B'
SI-12-1996	912 A, 912 F, 912 UL, 914 F, 914 UL	0	0	01.12.1996	n.a.	CANCELLED - Oil filter ROTAX 912 / 914 engine, superseded by SB-912-017/SB-914-037 UL, latest edition
SI-12-1997	914 F, 914 UL	0	0	01.07.1997	n.a.	CANCELLED - Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX engine Type 914 (series), superseded by SB-914-004 UL, latest edition
SI-13-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.07.1994	n.a.	Using auto fuel in ROTAX two cycle aircraft engine
SI-13-1996	912 A, 912 F, 912 UL, 914 F, 914 UL	0	2	23.06.2009	n.a.	Installation instructions of rev-counter part no. 966403 and 966408 for Rotax engine type 912 and 914 (Series)
SI-13-1997	914 F, 914 UL	0	0	01.12.1997	n.a.	CANCELLED - Introduction of a turbo charger with a modified wastegate on Rotax 914, superseded by SB-914-005 UL, latest edition
SI-14-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.07.1994	n.a.	ROTAX two-cycle aircraft engines crankshaft failures, piston seizures
SI-14-1997	912 A, 912 F, 912 UL, 914 F, 914 UL	0	1	01.03.1998	n.a.	Introduction of the single valve spring arrangement on Rotax engine type 912 and 914 (series)
SI-15-1994	447 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.11.1995	n.a.	Rev. counter for DUCATI ignition unit
SI-15-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	2	24.11.2010	n.a.	CANCELLED - Spark plugs for ROTAX engines 912/914 (Series), superseded by Maintenance Manual Line, latest edition
SI-16-1997	912 A, 912 F, 912 UL, 914 F, 914 UL	0	1	01.12.1997	n.a.	Introduction of a modified oil pressure sensor 912/914
SI-17-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.06.1994	n.a.	Weight, centre of gravity and moments of inertia of ROTAX UL-engines
SI-17-1997	277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL	0	0	01.11.1997	n.a.	Introduction of resistance spark plugs for Rotax 2-stroke engines
SI-18-1994	912 UL	1	0	01.11.1994	n.a.	Grounding cable for electronic module for ROTAX 912
SI-18-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	5	28.08.2006	n.a.	CANCELLED - Selection of Motor Oil and General Operating Tips for Rotax engines Type 912 and 914 (series), superseded by SI-912-016/SI-914-019 latest edition
SI-19-1994	582 UL	0	0	01.06.1994	n.a.	Cylinder and Piston for ROTAX 582 DCDCI
SI-19-1997	618 UL	0	0	01.12.1997	n.a.	Version without intake silencer 618 UL
SI-20-1994	912 A, 912 UL	0	3	01.10.1996	n.a.	Lubrication system for all ROTAX 912
SI-20-1997	277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.11.1997	n.a.	New flydat configuration for Rotax UL and aircraft engines
SI-21-1994	912 A, 912 F, 912 S, 912 UL, 912 ULS	0	0	01.07.1994	n.a.	CANCELLED - 912 carburetor fixation, superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-21-1997	912 A, 912 F, 912 UL, 914 F, 914 UL	0	1	01.11.1998	n.a.	Introduction of the mono hook circlip at ROTAX 912 and 914 series
SI-22-1994	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL	0	0	01.12.1994	n.a.	supply scope of ROTAX crankshafts
SI-22-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.11.1997	n.a.	Pressure oil line for hydraulic governor 912/914
SI-25-1994	912 UL	0	0	01.11.1994		Ensuring of a ground connection between screening box part no. 996 611 and engine
SI-25-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	11	18.07.2007	n.a.	CANCELLED - Running modifications on Rotax engine type 912 and 914 (series), superseded by SI-912-020/SI-914-022, latest edition
SI-26-1994	912 UL	0	0	01.11.1994	n.a.	TBO for ROTAX engine type 912 UL-series
SI-26-1997	912 UL, 914 UL	0	0	01.09.1998	n.a.	Supplementing the Maintenance Manual in regard to propeller gearbox without overload clutch
SI-27-1994	912 UL	1	0	01.03.1995	n.a.	Special inspection to increase the TBO for engine type 912 UL

document type	engine type	Issue	Revision	Date	P.no.	Title
SI-27-1997	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	17.07.2012	n.a.	CANCELLED - Oil level check for ROTAX engine type 912 and 914 (Series), superseded by relevant Maintenance Manual, latest edition
SI-2ST-001	582 UL, 618 UL	0	0	01.04.1999	n.a.	Installation instructions for the new design piston for 582 UL with mono hook piston pin circlip grooves
SI-2ST-002	582 UL, 618 UL	0	0	01.05.2000	n.a.	Change of the exhaust gasket on engine type 582 UL mod. 90/99 und type 618 UL
SI-2ST-003	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.08.2001		Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-2ST-004	447 UL, 503 UL, 582 UL, 618 UL	0	1	11.07.2006		Running modifications on ROTAX 2-stroke UL aircraft engines
SI-2ST-005	582 UL	0	0	01.12.2001		Modified rotary valve cover for ROTAX engine type 582 UL (replaced by SB-2ST-002)
SI-2ST-006	447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	0	0	22.12.2006		Airfilter for Rotax engine type 912 (Series) and 2-stroke UL aircraft engines
SI-2ST-007	447 UL, 503 UL, 532 UL, 582 UL, 618 UL	0	2	20.05.2008		Amendment on reduction gearbox type C and type E for ROTAX 2-stroke UL aircraft engines
SI-2ST-008	447 UL, 503 UL, 582 UL, 618 UL	0	0	08.04.2009	n.a.	Selection of suitable operating fluids for ROTAX 2-stroke UL engines
SI-2ST-009	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	09.11.2009	n.a.	Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912-001	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.04.1999	n.a.	Installation of rotary water pump seal and water pump impeller
SI-912-002	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.06.1999	n.a.	Verification of the Lubrication system and replacement of the oil pressure spring for engine type 912 and 914
SI-912-003	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	19.03.2009	n.a.	Oil line connections with UNF-threads (AN-8) for ROTAX engine types 912 and 914 (series)
SI-912-004	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.08.1999	n.a.	CANCELLED - Modified carburetor flange for Rotax engine type 912 (series) and Rotax engine type 914 (series), superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-912-005	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.02.2000	n.a.	Lubrication system for all ROTAX engine type 912 (series) and 914 (series)
SI-912-006	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	03.02.2009		Replacement of the circlip in the sprag clutch housing on ROTAX engine type 912 and 914 (series)
SI-912-007	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.08.2001		Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912-008	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	0	1	01.02.2002		Fuel pressure indication problems on ROTAX engine type 912 (series)
SI-912-009	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.10.2001		Introduction of a new rocker arm bushing for ROTAX engine type 912 and 914 (series)
SI-912-010	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	4	02.10.2012	n.a.	Oil change on Rotax engine type 912i, 912 and 914 (Series)
SI-912-011	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.03.2003	n.a.	Replacement of the gasket rings on the adaptor of the oil radiator for Rotax engine type 912 and 914 (series)
SI-912-012	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.03.2004	n.a.	Routine Modifications of the Bing constant depression carburetor on ROTAX engine type 912 and 914 (Series)
SI-912-013	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.04.2004	n.a.	Standardization of the ignition unit for ROTAX engine type 912 and 914 (Series)
SI-912-014	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.06.2004	n.a.	Optimizing of piston ring position for ROTAX engine type 912 and 914 (Series)
SI-912-015	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.06.2004		Increase of disk spring pre-tension in the gearbox on ROTAX engine type 912 and 914 (Series)
SI-912-016	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	5	08.03.2012	n.a.	Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series)
SI-912-017	447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR	0	0	22.12.2006		Airfilter for Rotax engine type 912 (Series) and 2-stroke UL aircraft engines
SI-912-018	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	02.10.2012		Purging of lubrication system for Rotax engine type 912i, 912 and 914 (Series)
SI-912-019	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	03.10.2007		Oil leakages in the area of the cylinder barrel for Rotax engine type 912 and 914 (Series)
SI-912-020	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	6	03.09.2012	n.a.	Running modifications on ROTAX engine type 912 and 914 (Series)
SI-912-021	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	09.11.2009	n.a.	Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912i-001	912 iS	0	0	08.03.2012	n.a.	Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series)

document type	engine type	Issue	Revision	Date	P.no.	Title
SI-912i-002	912 iS, 912 iSc	0	0	10.09.2012		B.U.D.S. Aircraft Installation Instructions for ROTAX Engine Type 912 i Series
SI-912i-003	912 iS, 912 iSc	0	0	10.09.2012		B.U.D.S. Aircraft Update for ROTAX Engine Type 912 i Series
SI-912i-004	912 iS, 912 iSc	0	0	02.10.2012		Purging for lubrication system for Rotax Engine Type 912i Series
SI-912i-005	912 iS, 912 iSc	0	0	02.10.2012	n.a.	Oil change on Rotax engine type 912i, 912 and 914 (Series)
SI-914-001	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.04.1999	n.a.	Installation of rotary water pump seal and water pump impeller
SI-914-002	914 F, 914 UL	0	0	01.04.1999	n.a.	Optimizing of mixture distribution
SI-914-003	914 F, 914 UL	0	1	15.04.2008	n.a.	Inspection and lubrication of Wastegate for ROTAX engine type 914 (Series)
SI-914-004	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.06.1999	n.a.	Verification of the Lubrication system and replacement of the oil pressure spring for engine type 912 and 914
SI-914-005	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	19.03.2009	n.a.	Oil line connections with UNF-threads (AN-8) for ROTAX engine types 912 and 914 (series)
SI-914-006	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.08.1999	n.a.	CANCELLED - Modified carburetor flange for Rotax engine type 912 (series) and Rotax engine type 914 (series), superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-914-007	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.02.2000	n.a.	Lubrication system for all ROTAX engine type 912 (series) and 914 (series)
SI-914-008	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	03.02.2009		Replacement of the circlip in the sprag clutch housing on ROTAX engine type 912 and 914 (series)
SI-914-009	277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.08.2001		Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-914-010	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.10.2001		Introduction of a new rocker arm bushing for ROTAX engine type 912 and 914 (series)
SI-914-011	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	4	02.10.2012	n.a.	Oil change on Rotax engine type 912i, 912 and 914 (Series)
SI-914-012	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.03.2003	n.a.	Replacement of the gasket rings on the adaptor of the oil radiator for Rotax engine type 912 and 914 (series)
SI-914-013	914 F, 914 UL	0	0	01.04.2003		Introduction of a new airbox for Rotax engine type 914 (series)
SI-914-014	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.03.2004	n.a.	Routine Modifications of the Bing constant depression carburetor on ROTAX engine type 912 and 914 (Series)
SI-914-015	914 F, 914 UL	0	0	01.12.2003		Introduction of a new airbox part no. 667167 for Rotax engine type 914 (Series)
SI-914-016	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.04.2004	n.a.	Standardization of the ignition unit for ROTAX engine type 912 and 914 (Series)
SI-914-017	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.06.2004	n.a.	Optimizing of piston ring position for ROTAX engine type 912 and 914 (Series)
SI-914-018	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	01.06.2004		Increase of disk spring pre-tension in the gearbox on ROTAX engine type 912 and 914 (Series)
SI-914-019	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	5	08.03.2012	n.a.	Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series)
SI-914-020	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	02.10.2012		Purging of lubrication system for Rotax engine type 912i, 912 and 914 (Series)
SI-914-021	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	03.10.2007		Oil leakages in the area of the cylinder barrel for Rotax engine type 912 and 914 (Series)
SI-914-022	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	6	03.09.2012	n.a.	Running modifications on ROTAX engine type 912 and 914 (Series)
SI-914-023	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	09.11.2009	n.a.	Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SL-2ST-001	277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.07.1999	n.a.	Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series)
SL-2ST-002	277 UL, 377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL	0	1	12.01.2005	n.a.	Documentations for ROTAX 2-stroke UL engines and certified 2-stroke aircraft engines
SL-2ST-003	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	01.07.2000	n.a.	CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition



document type	engine type	Issue	Revision	Date	P.no.	Title
SL-2ST-004	377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.12.1999	n.a.	Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL)
SL-2ST-005	447 UL, 503 UL, 582 UL, 618 UL	0	0	01.07.2001	n.a.	Running modifications on carburetors for ROTAX 2-stroke UL aircraft engines
SL-2ST-006	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	30.03.2009	n.a.	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-2ST-006	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	2	30.03.2009	n.a.	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-2ST-007	377 UL, 447 UL, 462 UL, 463, 503 UL, 505, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	4	21.12.2012		List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines
SL-2ST-008	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	3	13.07.2010		Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines
SL-2ST-009	447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	08.03.2012		Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines
SL-912-001	277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.07.1999	n.a.	Change of design of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series)
SL-912-002	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	28.05.2010	n.a.	Standardization of the crankshaft/piston pin and of the gearbox for ROTAX engine type 912/914 (Series)
SL-912-003	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	01.07.2000	n.a.	CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-912-004	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	15.04.2008	n.a.	Documentation for ROTAX engine type 912 and 914 (Series)
SL-912-005	377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.12.1999	n.a.	Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL)
SL-912-006	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.01.2000	n.a.	Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series)
SL-912-007	912 ULSFR	0	1	15.03.2011		ROTAX engine type 912 ULSFR - version for France
SL-912-008	912 A, 912 F, 912 S, 912 UL, 912 ULS	0	0	20.07.2000		CANCELLED - Operators and Maintenance Manual for ROTAX 912 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-912-009	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	01.12.2003	n.a.	CANCELLED - Coolant for ROTAX engine type 912 and 914 (Series), superseded by SB-912-043/SB-914-029, latest edition
SL-912-010	912 S, 912 ULS, 912 ULSFR	0	0	01.02.2003		Identifying abnormal vibrations on aircrafts equipped with Rotax engine type 912 S/ULS/ULSFR
SL-912-011	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	02.10.2012	n.a.	Use of an oil thermostat for Rotax engine type 912i, 912 and 914 (Series)
SL-912-012	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	30.03.2009	n.a.	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-912-012	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	2	30.03.2009	n.a.	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-912-013	377 UL, 447 UL, 462 UL, 463, 503 UL, 505, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	4	21.12.2012		List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines
SL-912-014	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	3	13.07.2010		Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines
SL-912-015	447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	08.03.2012		Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines

document type	engine type	Issue	Revision	Date	P.no.	Title
SL-912-016	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	28.07.2009	n.a.	Essential information regarding engine behavior, performance and manifold pressure data for ROTAX engines type 912 und 914 (Series)
SL-912i-001	912 iS	0	0	08.03.2012		Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines
SL-912i-002	912 iS, 912 iSc	0	0	02.10.2012	n.a.	Use of an oil thermostat for Rotax engine type 912i, 912 und 914 (Series)
SL-912i-003	912 iS	0	0	08.03.2012		Warranty conditions for ROTAX 912 i Series - Warranty coverage is provided by the OEM. Please contact your aircraft manufacturer for warranty.
SL-914-001	277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	1	01.07.1999	n.a.	Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series)
SL-914-002	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	28.05.2010	n.a.	Standardization of the crankshaft/piston pin and of the gearbox for ROTAX engine type 912/914 (Series)
SL-914-003	185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	01.07.2000	n.a.	CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-914-004	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	2	15.04.2008	n.a.	Documentation for ROTAX engine type 912 and 914 (Series)
SL-914-005	377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.12.1999	n.a.	Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL)
SL-914-006	912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL	0	0	01.01.2000	n.a.	Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series)
SL-914-007	914 F, 914 UL	0	0	01.07.2000		CANCELLED - Operators and Maintenance Manual for ROTAX 914 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-914-008	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	01.12.2003	n.a.	CANCELLED - Coolant for ROTAX engine type 912 and 914 (Series), superseded by SB-912-043/SB-914-029, latest edition
SL-914-009	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	02.10.2012	n.a.	Use of an oil thermostat for Rotax engine type 912i, 912 and 914 (Series)
SL-914-010	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	30.03.2009	n.a.	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-010	447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	2	30.03.2009	n.a.	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-011	377 UL, 447 UL, 462 UL, 463, 503 UL, 505, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	4	21.12.2012		List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-012	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	3	13.07.2010		Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines
SL-914-013	447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	1	08.03.2012		Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-014	912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL	0	0	28.07.2009	n.a.	Essential information regarding engine behavior, performance and manifold pressure data for ROTAX engines type 912 und 914 (Series)